

LDW5F  
12.3.412.1  
4-24-02

**From:** "Scott Dwyer" <sdwyer@kleinfelder.com>  
**To:** <hvoges@retec.com>  
**Date:** Wednesday, April 24, 2002 11:44:44 AM  
**Subject:** Long Painting Monitoring Well Information

As you requested, here are the monitoring well elevations (top of casing) for the wells on the Long Painting facility at 8025 - 10th Ave S in Seattle:

MW-1, 13.51  
MW-2, 12.05  
MW-3, 12.85  
MW-5, 12.27  
MW-6 (dry)  
MW-8, 12.48

The elevations were based on a USGS benchmark located approximately 1/2 mile from the site. Water levels on the map in our site investigation report were measured on July 19, 2000 between 10:00 AM and 10:50 AM.

If you need anything else, let me know.

Scott Dwyer

---

Warning: Information provided via electronic media is not guaranteed against defects including translation and transmission errors. In addition, this electronic communication and its attachments are forwarded to you without passing through our standard review process. Design data and recommendations included herein should not be used for final design.

If the reader is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this information in error, please notify the sender immediately.

**CC:** Keith Moxon <KMoxon@buckgordon.com>, <mikec@longpainting.com>

USEPA SF



1410114